ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
1

Ward Name
Kempegowda Ward

Street ID
W0384, W0337, W0307, W0392, W0367, W0488, W0373, W

Street Name
Own Use Rd, NA, 2nd Crs, East Park Reje Lyt, 6th Crs, Muthkurappa Lyt, Dr Ambekdar Govt Ashraya Colo

Significant Landmark
Neharunagara, Suggappa Layout and Gandhinagara

Segment No.
1/C-W0384/S044320

Total Length (m)
350.13

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	22.87	77.596572	13.099118	77.596486	13.098930	WO488	END
2	53.01	77.596907	13.098703	77.596457	13.098889	WO392	END
3	81.73	77.593903	13.099314	77.593619	13.098635	WO307	END
4	103.32	77.593200	13.099116	77.594107	13.098828	WO402	END
5	89.20	77.596947	13.097987	77.597752	13.097820	WO384	END

Work Details

History of Road / Lane / Circles

Name of the Work
Providing and fixing missing kerb stones, covering slabs and desilting of drains at yelahanka old town and surrounding areas in kempegowda ward no -01

Sanctioned Estimated Amount (Rs.)
1600000

Sanctioned Year
2020-21

Year
2020 - 2021

Type of Work
Others

Other Work Type

Tender

Work Details

Job No. / Work Code
00-20-000105

Work Order No.
BBMP/EE/YNK-D/EPMT-01/WO57/2020-21

Work Order Date
19/06/2020

Period of Extention

Defect Liability Period From
29/12/2020

Defect Liability Period To
28/12/2021

Multiple road involved with the same Job No/ Work Code #
No

Contractor Details

Name of Contractor
H S PRAKASH

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)
0.00

Zone: YELAHANKA Ward No: 1 Ward Name: Kempegowda Ward Street ID: W0384, W0337, W0307, W0392,

Asst. Executive Engineer
Yelahanka Sub. Division
(BBMP Ynk. Zn)
Yelahanka, Bangalore

Any Other Information

Number of Trees

0

Name

mallinath malkapur

Remarks

Date of Inspection

28/12/2020

Category	Image	Photo Remark
Segment Start		Location was not determined.
Segment Start		Location was not determined.
Segment Start		Location was not determined.
Segment Start		Location was not determined.
Segment Start		Location was not determined.
Segment Start		Location was not determined.
Segment Start		Location was not determined.
Segment Start		Location was not determined.

Zone: YELAHANKA **Ward No:** 1 **Ward Name:** Kempegowda Ward **Street ID:** W0384, W0337, W0307, W0392,

Asst. Executive Engineer
Yelahanka Sub. Division
(BBMP Ynk. Zn)
Yelahanka, Bangalore

9901100660 E-Mail ID

Field Inspection Details

Number of Trees

0

Any Other Information

Name

mallinath malkapur

Date of Inspection

28/12/2020

Remarks

Category	Image	Photo Remark
Segment Start		Location was not determined
Segment Start		Location was not determined
Segment Start		Location was not determined
Segment Start		Location was not determined
Segment Start		Location was not determined
Segment Start		Location was not determined
Segment Start		Location was not determined
Segment Start		Location was not determined

Zone: YELAHANKA **Ward No:** 1 **Ward Name:** Kempegowda Ward **Street ID:** W0384, W0337, W0307, W0392,

Asst. Executive Engineer
Yelahanka Sub. Division
(BBMP Ynk. Zn)
Yelahanka, Bangalore